



a division of Englobe

*Proud of Our Past... Building the Future*

# **INFRASTRUCTURE AUDIT**

Village of Bittern Lake

# Project Objective

- ❑ Assess the current condition of key infrastructure
- ❑ Recommend infrastructure upgrades considering:
  - Existing condition
  - Current standards and guidelines
- ❑ Develop cost estimates and priority for completion
- ❑ Allocation of funds to infrastructure with the most need
- ❑ Grant funding

# Study Scope

- ❑ Introductory meeting with Village staff
- ❑ Review available information
- ❑ Inspect key infrastructure
- ❑ Identify required upgrades and maintenance
- ❑ Develop a Class D Cost Estimate
- ❑ Develop a 20 – Year Capital Plan

# Key Infrastructure

- ❑ Potable Water Supply and Distribution
- ❑ Sanitary Collection and Treatment
- ❑ Stormwater
- ❑ Transportation
- ❑ Village owned buildings
- ❑ Waste Transfer Site
- ❑ Vehicles and Equipment

# Historical Water Consumption

- ❑ ADD = Average Day Demand
- ❑ MDD = Max Day Demand
- ❑ PHD = Peak Hour Demand
- ❑ Lpcd = Litres per capita per day

	Historical Consumption (Lpcd)	Audit Values (Lpcd)
ADD	228	250
MDD	552	500
PHD	1,104	1,000

# Water Supply and Storage

- ❑ City of Camrose
- ❑ Reservoir and Pump Station
- ❑ Reservoir Capacity = 550 m<sup>3</sup>
- ❑ Required Storage for Typical Consumption = 163 m<sup>3</sup>
- ❑ Storage recommended for Fire Demand = 540m<sup>3</sup>




# Pump Station

- ❑ Adequate Condition Overall
- ❑ Continue Maintenance
- ❑ Implement SCADA



# Water Distribution System



- ❑ Record Drawings
- ❑ GPS Survey
  - Valves
  - Hydrants
- ❑ Hydrant Flow Testing
- ❑ History of breaks or leaks



# Water System Modeling

- ❑ System Layout
- ❑ Historical Water Demands
- ❑ Fire Flows
- ❑ Hydrant Testing
- ❑ Results
  - Adequate Pressure
  - Limited Fire Flow




# Water System Improvements

- ❑ Looping
- ❑ Increasing Watermain Diameters
- ❑ Additional Hydrants
- ❑ Fire Demand Review



# Sanitary Collection




- 2015 Drawings
- GPS Survey
  - Manholes
- Manhole inspections
- Sanitary main camera inspection footage



# Manhole Condition Assessment

- ❑ 21% Good Condition
- ❑ 45% Fair Condition
- ❑ 24% Poor Condition
- ❑ 10% couldn't be inspected
- ❑ 3 manholes for replacement
- ❑ 13 manholes for repairs

# Sanitary Main Camera Inspection




- ❑ Cracks
- ❑ Exposed Gaskets
- ❑ Breaks
- ❑ Joint offsets/ gaps
- ❑ Sags
- ❑ Intrusions
  - Services
  - Roots
  - Mineral deposits

# Sanitary Main Condition Assessment

Rating	Percentage (%)
Good	22
Fair	37
Poor	34
Not Rated	7

- Replacement
- Relining
- Spot Repairs
- Modeling

# Sanitary Collection System Priority Level





# Sanitary Treatment



- ❑ Single Cell
- ❑ Capacity
- ❑ Configuration

# Lagoon Condition

- ❑ Significant Vegetation Growth
- ❑ No Erosion
- ❑ Inlet Structure
- ❑ Fence Requires Repair



# Stormwater Assessment

- Contour Data
- System layout
  - Drainage paths
  - Catch basins
  - Culverts
- GPS Survey
- Collect rainfall data
  - Intensity – Duration – Frequency Curves
  - Various Events



# Stormwater Model

- ❑ Model
- ❑ Results
  - Flow rates and volumes
  - Areas and extents of ponding
- ❑ Model improvements



# Transportation Infrastructure



- ❑ Field survey
- ❑ Record surface deformations
- ❑ Summarize pavement condition
- ❑ Create maps of Village roads and sidewalks

# Roadway Condition

- Recommend rehabilitation
  - Full Mill and Overlay



# Building Inspections

- Village owned buildings:
  - Village Office
  - Public Works Shop
  - Community Hall
  - Skate Park/ Skating Rink
  - Cemetery Site
  
- Assessment:
  - Civil
  - Structural
  - Mechanical
  - Electrical

# Village Office

- ❑ Deficiencies:
  - Exterior Siding
  - Crack in the Foundation
  - Doors and Overhead Doors
  - Carpet
  - Furnace
  - Washroom Exhaust Fan
  - Condenser
  - Exit Sign Lighting
  - Light Fixtures





# Public Works Shop



- Deficiencies:
  - Mezzanine Column
  - Exhaust Switch

# Community Hall

- Deficiencies:
  - Railing Fasteners
  - Exterior Siding
  - Painted Surfaces
  - Possible Hazardous Materials
  - Furnace
  - Washroom Exhausts
  - Light Fixtures



# Skate Park and Skating Rink



- Deficiencies:
  - Exterior Siding

# Cemetery



- Deficiencies:
  - None

# Other Infrastructure

- Other Assessments
  - Waste Transfer Site
  - Inventory of Village Owned Equipment



# Phase I ESA

## □ Completed for Village Owned Sites:

- Skate Park
- Village Office
- Public Works Compound
- Public Works Shop
- Community Hall
- Waste Transfer Site
- Cemetery

## □ Low Environmental Risk:

- Skate Park
- Public Works Shop
- Waste Transfer Site
- Cemetery

## □ Village Office

- Possible soil contamination
- Possible hazardous materials

## □ Public Works Compound

- Possible soil contamination

## □ Community Hall

- Possible soil contamination
- Possible hazardous materials

# Deliverables

- Report
  - Summary of findings
  - Figures for each system
  - Cost Estimates for each system
  - 20-Year Capital Plan
- Inspection Reports
  - Hydrant flow test reports
  - Manhole inspections
- Models
  - Water System
  - Sanitary System
  - Stormwater